ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0363, W0361, W0198, W0367, W0365	R H B Colcny 1st Main Rd, Chikka Muniswammappa Lyt, 1st Crs, NA, Chikka Muniswammappa Lyt, 2nd Crs	BEL 5th Block
Segment No.	**Total Length (m)**	
9/C-W0363/S090845	276.87	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	276.87	77.557361	13.074160	77.559833	13.073605	5th Block BEL	main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC drain from 11th A Cross to 5th Main BEL layout 3rd Block in ward no. 09 Vidyaranyapura, Vidyaranyapura sub division	2700000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Rcc drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	Rcc drain	009-17-000039
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/66/2017-18	31/05/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	30/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
T.K.Shankarappa		0.00
Phone No.	**E-Mail ID**	
9964440879		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0363, W0361, W0198, W0367,

umber of Trees	Any Other Information	Name
		krishnappa
D of Inspection	Remarks	
20/07/2017		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0363, W0361, W0198, W0367,

Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	20/07/2017	19/08/2017	Approved
SE	K.M.Vasu	20/07/2017	19/08/2017	complete
EE	H.T.Mohandas	20/07/2017	19/08/2017	complete
AEE	Shivakumar m gowdar	20/07/2017	19/08/2017	verify
AE	Krishnappa	20/07/2017	19/08/2017	Mobile verification done
AE	Krishnappa	20/07/2017	19/08/2017	Forward

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0363, W0361, W0198, W0367,